



Automatic test of
drive shafts
with eddyliner® P 4




- for hardness,
- hardness depth and
- hardness runout in the spline





Feeding of the parts is effected via gravity roller conveyor directly after the induction hardening process.



The test coils automatically move into test position. After the test, the OK-parts are forwarded to the tempering oven.